



Cleaner for welded joint inspection No. 1

Cleaner for welded joint inspection No. 1.

The overall inspection, is performed by carrying out three different operational stages; the cleaner is needed for stage No. 1 where the welded joint is subjected to thorough cleaning from oil tracks, dirt, lining or other residuals.

The product has no chemical reaction if combined with equivalent products of other brands.



Code	€	Pz.	Package	Control phase no.
T901310400	€	12	Spray 400 ml	1 of 3



Penetrant for welded joint inspection No. 2

Penetrant for welded joint inspection No. 2.

The overall inspection is performed by carrying out 3 different operational stages; the penetrant is needed for stage No. 2 where the welded joint, after being cleaned, is spread with this product which has the peculiarity of penetrating in all of the metallurgical imperfections.

The product has no chemical reaction if combined with equivalent products of other brands.



Code	€	Pz.	Package	Control phase no.
T901220400	€	12	Spray 400 ml	2 di 3



Detector for welded joint inspection No. 3

Detector for welded joint inspection No. 3.

The overall inspection is performed by carrying out 3 different operational stages; the detector is needed for the final stage No. 3 where the welded joint, after being cleaned to remove the penetrant in excess, and subsequently dried, is spread with this product which enables highlighting the remaining penetrant in discontinuities and expands it on surface, thus making the fault evident.

The product has no chemical reaction if combined with equivalent products of other brands.



Code	€	Pz.	Package	Control phase no.
T901230400	€	12	Spray 400 ml	3 di 3



Cleanox degreasing

Cleanox degreasing for treatment of stainless steel surface to be welded, or before the use of picking agents and passive-making; promotes their perfect adherence and subsequent chemical action through the thorough removal of oil tracks and grease.

To be weaked in water solution, approximately to 20%÷30%, applied with a sponge or atomized on the part involved; after leaving the product to work for about 10-15 min. the product shall be rinsed generously and left to dry away from sun beams and climate agents.



Code	€	Package (Kg)	Type
T901250060	€	6	liquid
T901250300	€	30	liquid

